

Re: TP hydrant inspection

2 emails

ray.worthen <ray.worthen@zoho.com >

ray.worthen <ray.worthen@zoho.com >

Tue, 04 Aug 2026 3:47:05 PM -0600

To "Highlands Water Co." <highlandswaterco@gmail.com>

Cc "Larry Parker" <lpltd@sprintmail.com>, "ktwood55" <ktwood55@gmail.com>

Mr. Hadley,

Thank you for sending this it is very helpful and we'll keep it on file.

NFPA is the National Fire Protection Association.
It is referenced in the 2024 Utah State Fire Code Section 507
along with the IFC, the International Fire Code.

I am concerned about the condition of some of the hydrants which show a great deal of rust and one is leaning quite severely.
However we will take your word that all are operational and have been tested as required by Utah Code.

Thank you again

Ray Worthen

From: Highlands Water Co. <highlandswaterco@gmail.com>

To: "ray.worthen" <ray.worthen@zoho.com>

Date: Tue, 04 Aug 2026 15:13:09 -0600

Subject: TP hydrant inspection

> Mr Worthen,

> My Name is Nate Hadley I am the certified water operator for Highlands Water Co. I have worked for the water company since 2019 and I have exercised, flushed or pressure tested every hydrant in our system multiple times. I have attached my record for trappers point subdivision below.

> I am not familiar with NFPA. I do not believe that they are a regulatory body. However we are regulated by the Utah Division of Drinking Water and we follow the DDW and AWWA recommendations for waterline installation and operations, this includes fire hydrants. Since the hydrants are ours to maintain and operate, outside of an emergency, no one should connect to, open or operate a hydrant without permission from Highlands Water Co.

> I have pasted the hydrant records for trapper point through 2025 below.

> Feel free to contact me if you have any questions.

> Nate Hadley Highlands Water Co.801-458-0175

> Trappers point Hydrant operation record

> 2020

> Jan

> 6815 frontier Dr Hydrant flushed following leak repair

> 6883 Trappers circle Hydrant flushed following leak repair

> 6933 Bear springs Hydrant flushed following leak repair

> 5272 Frontier Dr Hydrant flushed following leak repair

> 5242 Frontier Dr Hydrant flushed following leak repair

> 5142 Frontier Dr Hydrant flushed following leak repair

> 6850 Black powder Hydrant flushed following leak repair

> Feb

- > 6815 frontier Dr Hydrant flushed following leak repair
- > 6883 Trappers circle Hydrant flushed following leak repair
- > 6933 Bear springs Hydrant flushed following leak repair
- > 5272 Frontier Dr Hydrant flushed following leak repair
- > 5242 Frontier Dr Hydrant flushed following leak repair
- > 5142 Frontier Dr Hydrant flushed following leak repair
- > 6850 Black powder Hydrant flushed following leak repair
- >
- > Dec
- > 5242 Frontier Hydrant exercise and pressure tested psi 85.
- > 6815 frontier Dr hydrant exercises and flushed
- >
- > 2021
- > Apr
- > 6815 Frontier Dr Flush hydrant for 4 hrs until water cleared up due to customer call
- > 6933 Bear springs Flush hydrant for 4 hrs until water cleared up due to customer call
- > 6883 Trappers circle Flush hydrant for 4 hrs until water cleared up due to customer call
- > 6850 Black powder Flush hydrant for 4 hrs until water cleared up due to customer call
- >
- > July
- > 6815 Frontier Dr exercise, flush and pressure hydrant psi 125
- >
- > aug
- > 5228 rendezvou hydrant exercise and flushed
- > 6883 Trappers circle hydrant exercise and flushed
- > 6933 Bear springs hydrant exercise and flushed
- > 6815 Frontier Dr Exercise, and flush
- >
- > Dec
- > 6850 Black powder Exercise, and flush
- > 6815 Frontier Dr Exercise, and flush
- >
- > 2022
- > May
- > 6850 Black powder Exercise, and flush
- > 6815 Frontier Dr Exercise, and flush
- >
- > Aug
- > 6883 Trappers circle Exercise, and flush
- >
- > sept
- > 6815 Frontier Dr Flush hydrant after leak repair
- >
- > Oct
- > 5242 Frontier Dr Exercise, flush & pressurised hydrant 95 psi
- >
- > Nov
- > 6883 Trappers circle Exercise, and flush
- > 6815 Frontier Dr Flush hydrant after leak repair
- >
- > 2023
- > May
- > 6815 Frontier Dr Flush hydrant after leak repair
- > 6883 Trappers circle Flush hydrant after leak repair
- > 6850 Black powder Flush hydrant after leak repair
- > 6933 Bear springs Flush hydrant after leak repair
- >
- > Nov
- > 6815 Frontier Dr Exercise, and flush
- > 6883 Trappers circle Exercise, and flush
- >
- > 2024

- > Jan
- > 5228 rendezvou hydrant exercise and flushed
- > 6815 Frontier Dr Exercise, and flush
- >
- > May
- > 6815 Frontier Dr Exercise, and flush
- >
- > June
- > 5242 Frontier Dr Exercise, and flush
- > 6815 Frontier Dr Exercise, and flush
- >
- > July
- > 6710 Frontier Exercise, and flush
- > 6815 Frontier Dr hydrant exercise and flushed
- > 6883 Trappers circle hydrant exercise and flushed
- > 6850 Black powder Flush hydrant after leak repair
- > 6933 Bear springs Flush hydrant after leak repair
- > 5242 Frontier Dr hydrant exercise and flushed
- > 5142 Frontier Dr hydrant exercise and flushed
- > 5272 Frontier Dr. Hydrant meter installed for water line project, hydrant operated mutiple times a day for 2 months.
- >
- > Aug
- > 5142 Frontier Dr Hydrant meter installed for power line project, hydrant operated mutiple times a day for 3 weeks.
- > 6933 Bear springs Flush hydrant after valve repair
- > 5272 Frontier Dr. Flush hydrant after valve repair
- > 6815 Frontier Dr Flush hydrant after valve repair
- >
- > sept
- > 5142 Fronier Dr Flush hydrant after water line tie ine
- > 6933 Bear springs Flush hydrant after water line tie ine
- > 5272 Frontier Dr. Flush hydrant after water line tie ine
- > 6815 Frontier Dr Flush hydrant after water line tie ine
- > 6850 Black powder Flush hydrant after water line tie ine
- >
- > Dec
- > 6815 Frontier Dr Fire flow tested for frontier estates
- > 6727 Frontier Fire flow tested for frontier estates
- >
- > 2025
- > Jan
- > 5142 Frontier Exercise, and flush
- > 6933 Bear springs Exercise, and flush
- > 5242 Frontier Exercise, and flush
- > 5272 Frontier Exercise, and flush
- > 6881 Frontier Exercise, and flush
- > 6815 Frontier Exercise, and flush
- > 5228 Rendezvous Exercise, and flush
- > 5184 Trappers cir. Exercise, and flush
- > 6883 Trappers Cir Exercise, and flush
- > 6850 Black powder Exercise, and flush
- >
- > June
- > 6933 Bear springs Flush hydrant after valve repair
- > 6815 Frontier Flush hydrant after valve repair
- > 6850 Black powder Flush hydrant after valve repair
- >
- > Sept
- > 5142 Fronier Dr Flush hydrant after water line tie in
- > 6933 Bear springs Flush hydrant after water line tie in
- > 5272 Frontier Dr. Flush hydrant after water line tie in

- > 6815 Frontier Dr Flush hydrant after water line tie in
- > 6850 Black powder Flush hydrant after water line tie in
- >
- > Nov
- > 6815 Frontier Fire flow tested for range development
- > 6670 Frontier Fire flow tested for range development
- > 6529 Frontier Fire flow tested for range development
- > 6588 Frontier Fire flow tested for range development
- >
- >
- >

Highlands Water Co. <highlandswaterco@gmail.com >

Tue, 04 Aug 2026 3:13:50 PM -0600

To "ray.worthen"<ray.worthen@zoho.com>

Mr Worthen,

My Name is Nate Hadley I am the certified water operator for Highlands Water Co. I have worked for the water company since 2019 and I have exercised, flushed or pressure tested every hydrant in our system multiple times. I have attached my record for trappers point subdivision below.

I am not familiar with NFPA. I do not believe that they are a regulatory body. However we are regulated by the Utah Division of Drinking Water and we follow the DDW and AWWA recommendations for waterline installation and operations, this includes fire hydrants. Since the hydrants are ours to maintain and operate, outside of an emergency, no one should connect to, open or operate a hydrant without permission from Highlands Water Co.

I have pasted the hydrant records for trapper point through 2025 below.

Feel free to contact me if you have any questions.

Nate Hadley
Highlands Water Co.
801-458-0175

Trappers point Hydrant operation record
2020

Jan

6815 frontier Dr	Hydrant flushed following leak repair
6883 Trappers circle	Hydrant flushed following leak repair
6933 Bear springs	Hydrant flushed following leak repair
5272 Frontier Dr	Hydrant flushed following leak repair
5242 Frontier Dr	Hydrant flushed following leak repair
5142 Frontier Dr	Hydrant flushed following leak repair
6850 Black powder	Hydrant flushed following leak repair

Feb

6815 frontier Dr	Hydrant flushed following leak repair
6883 Trappers circle	Hydrant flushed following leak repair
6933 Bear springs	Hydrant flushed following leak repair
5272 Frontier Dr	Hydrant flushed following leak repair
5242 Frontier Dr	Hydrant flushed following leak repair

5142 Frontier Dr Hydrant flushed following leak repair
 6850 Black powder Hydrant flushed following leak repair

Dec

5242 Frontier Hydrant exercise and pressure tested psi 85.
 6815 frontier Dr hydrant exercises and flushed

2021

Apr

6815 Frontier Dr Flush hydrant for 4 hrs until water cleared up due to customer call
 6933 Bear springs Flush hydrant for 4 hrs until water cleared up due to customer call
 6883 Trappers circle Flush hydrant for 4 hrs until water cleared up due to customer call
 6850 Black powder Flush hydrant for 4 hrs until water cleared up due to customer call

July

6815 Frontier Dr exercise, flush and pressure hydrant psi 125

aug

5228 rendezvou hydrant exercise and flushed
 6883 Trappers circle hydrant exercise and flushed
 6933 Bear springs hydrant exercise and flushed
 6815 Frontier Dr Exercise, and flush

Dec

6850 Black powder Exercise, and flush
 6815 Frontier Dr Exercise, and flush

2022

May

6850 Black powder Exercise, and flush
 6815 Frontier Dr Exercise, and flush

Aug

6883 Trappers circle Exercise, and flush

sept

6815 Frontier Dr Flush hydrant after leak repair

Oct

5242 Frontier Dr Exercise, flush & pressurised hydrant 95 psi

Nov

6883 Trappers circle Exercise, and flush
 6815 Frontier Dr Flush hydrant after leak repair

2023

May

6815 Frontier Dr Flush hydrant after leak repair
 6883 Trappers circle Flush hydrant after leak repair
 6850 Black powder Flush hydrant after leak repair
 6933 Bear springs Flush hydrant after leak repair

Nov

6815 Frontier Dr Exercise, and flush
 6883 Trappers circle Exercise, and flush

2024

Jan

5228 rendezvou hydrant exercise and flushed
 6815 Frontier Dr Exercise, and flush

May

6815 Frontier Dr Exercise, and flush

June

5242 Frontier Dr Exercise, and flush
 6815 Frontier Dr Exercise, and flush

July

6710 Frontier Exercise, and flush
 6815 Frontier Dr hydrant exercise and flushed
 6883 Trappers circle hydrant exercise and flushed
 6850 Black powder Flush hydrant after leak repair
 6933 Bear springs Flush hydrant after leak repair
 5242 Frontier Dr hydrant exercise and flushed
 5142 Frontier Dr hydrant exercise and flushed
 5272 Frontier Dr. Hydrant meter installed for water line project, hydrant operated mutiple times a day for 2 months.

Aug

5142 Frontier Dr Hydrant meter installed for power line project, hydrant operated mutiple times a day for 3 weeks.
 6933 Bear springs Flush hydrant after valve repair
 5272 Frontier Dr. Flush hydrant after valve repair
 6815 Frontier Dr Flush hydrant after valve repair

sept

5142 Fronier Dr Flush hydrant after water line tie ine
 6933 Bear springs Flush hydrant after water line tie ine
 5272 Frontier Dr. Flush hydrant after water line tie ine
 6815 Frontier Dr Flush hydrant after water line tie ine
 6850 Black powder Flush hydrant after water line tie ine

Dec

6815 Frontier Dr Fire flow tested for frontier estates
 6727 Frontier Fire flow tested for frontier estates

2025

Jan

5142 Frontier Exercise, and flush
 6933 Bear springs Exercise, and flush
 5242 Frontier Exercise, and flush
 5272 Frontier Exercise, and flush
 6881 Frontier Exercise, and flush
 6815 Frontier Exercise, and flush
 5228 Rendezvous Exercise, and flush
 5184 Trappers cir. Exercise, and flush
 6883 Trappers Cir Exercise, and flush

6850 Black powder Exercise, and flush

June

6933 Bear springs Flush hydrant after valve repair

6815 Frontier Flush hydrant after valve repair

6850 Black powder Flush hydrant after valve repair

Sept

5142 Fronier Dr Flush hydrant after water line tie in

6933 Bear springs Flush hydrant after water line tie in

5272 Frontier Dr. Flush hydrant after water line tie in

6815 Frontier Dr Flush hydrant after water line tie in

6850 Black powder Flush hydrant after water line tie in

Nov

6815 Frontier Fire flow tested for range development

6670 Frontier Fire flow tested for range development

6529 Frontier Fire flow tested for range development

6588 Frontier Fire flow tested for range development